

L2S from Zentrix

Problem found of 1 out of 8

Hybrid #4

Clk pad is open as indicated
on diagram (all green pads are
supposed to be connected)

Open pads (Clk)

